



Anderson Radiology
AndersonRad.com


Quick Notes:

Patient Chart

Click on the patient's name, in blue, from any Worklist to access their patient chart.

Inside the patient chart, you will be able to view reports and visit forms and view the DICOM images

by clicking the  icon.




The screenshot displays the patient chart for Buddy Zztest (08-2000020). The interface includes a top navigation bar with tabs for ID Card, Consent Forms, Portal Uploads, Financial, Patient Education, Ultrasound, Tech Workflow, Insurance, Reports, Orders / Referring Clinicals, e-Forms Clinicals, Screening, Prescreening Questionnaire, Medical Records, and Patient Study Viewer. The 'Patient Study Viewer' tab is active, showing a list of studies under 'Documents & Images'. The first study is 08-6259 - MR (1), dated 4/7/2026 8:00:00 AM, authored by Shramek Jeffrey, and signed.

The patient information section on the right shows 'No identification on file' and 'Buddy zztest Patient Info'. The patient's MRN is 08-2000020, and their DOB is 01/01/2000 (26 y). The patient is Male, and their language is English. The contact information section shows a home phone number of (777) 777-7777 and a work phone number. The address is 123456 Test House Road, Summerville, SC 29485. The email is not provided. The primary contacts section shows 'No contacts added' and a button to '+ Add Contact'.

The main content area displays the following information:

- Record #:** 08-2000020 **Name:** Buddy zztest **DOB:** 01/01/2000
- EXAM:** MRA Head and Neck With Contrast
- REASON FOR EXAM:** W56.4: Contact with shark
- COMPARISON:** None.
- TECHNIQUE:** 2D and 3D time-of-flight MR arteriography of the neck and head with volume rendered and rotating 3D MIP reconstructions independent 3D workstation performed after the intravenous administration of contrast.
- FINDINGS:** Normal evaluation of the transverse aortic arch and great vessels. Normal diameter and smooth lumens of the extracranial vertebral and basilar arteries with no evidence for dissection, aneurysm, pseudoaneurysm, arteritis, or fibromuscular dysplasia. Alternating diameter narrowings and caliber changes of the vertebral arteries within the neck compatible with fibromuscular dysplasia. There is also atherosclerotic plaque within the proximal right ICA producing a 40% diameter stenosis. Suggestion of a subtle erosion into atherosclerotic plaque at this site may indicate intraplaque ulceration. This this places the patient at increased risk of thromboembolic disease to the brain and CVA.
- 15 mm patent aneurysm of the right MCA bifurcation is directed posteriorly and inferiorly. In addition, there is 50% narrowing of the left A1 ACA with poststenotic dilatation.**
- Infundibulum of the right posterior communicating artery.**
- IMPRESSION:**
 1. 15 mm patent right MCA bifurcation aneurysm.
 2. 50% narrowing of the left A1 ACA with poststenotic dilatation.
 3. Fibromuscular dysplasia of the vertebral arteries within the neck.
 4. Atherosclerotic plaque within the proximal right ICA producing a 40% diameter stenosis. Suggestion of intraplaque ulceration. This places the patient at increased risk of thromboembolic disease to the brain and CVA.
- This is an electronically verified report by [redacted] at 4/8/2026 12:14 PM
- [redacted], MD

Notes

- Clicking Patients under Search at the top left will show all your recent patients.
- If you forget your password, click the Forgot Password link on the main login page to reset your password.
- If you know your password and want to change it, log in and click your name in the top right corner. From here, click Change Password.
- Clicking the DICOM buttons will launch a window to view exam images in iConnect.
- Reports show in the patient chart without the header information. Printing them will include the header information, to include the facility and patient information.
- You can print any documents from the patient chart.
- You cannot modify the patient's demographics; you can only view them.
- You can add additional filters in any view by clicking the  button.
- If you need to reset your multi-factor authentication phone number, please contact your marketing representative so we can update your account.